

Phu Thuan - VIETNAM

Before

zone suffering from typhoons; destruction of houses and infrastructures
March 2007



After the laying of
6 STABIPLAGE®
structures

August 2007



5 months later

Stabilisation of the coast and
natural return to a sediment accretion
of the beach
January 2008

